

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/23/2016
Document Number:
679700225
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>443741</u>	<u>332061</u>	<u>ALLISON, RICK</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 10590
 Name of Operator: GRIZZLY OPERATING LLC
 Address: 1944 26TH AVENUE CT
 City: GREELEY State: CO Zip: 80634

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Reale, Jeff	970-669-3318	jeff@mistymountainop.com	Agent-Grizzly Operating
Binschus, Chris		chris.binschus@state.co.us	COGCC Reclamation Specialist

Compliance Summary:

QtrQtr: NENW Sec: 17 Twp: 5N Range: 64W

Inspector Comment:

COGCC Environmental Staff Inspection of Goza Land Application Site for Grizzly Operating. Data submitted by Operator demonstrates that the soil in the Land Application Area complies with the Table 910-1 Concentration Levels. A site inspection confirms that E&P Waste has been incorporated. The Operator has demonstrated that the facility meets the environmental closure requirements; however, the facility will remain "Active" status until a final reclamation review has been performed. A sundry notice request for final reclamation review of the site should be entered to trigger the reclamation review.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269940	WELL	PR	12/05/2004	GW	123-21779	STEINMETZ 21-17	PR
443741	LAND APPLICATION SITE	AC	10/27/2015	-	-	Goza Beneficial Reuse Area	EI

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 443741

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 443741 Type: LAND API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume: Comment: Corrective Action: Date: Reportable: GPS: Lat Long Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB): Comment: Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed: Land Use: Comment: 1003a. Waste and Debris removed? CM CA CA Date Unused or unneeded equipment onsite? CM CA CA Date Pit, cellars, rat holes and other bores closed? CM CA CA Date Guy line anchors marked? CM CA CA Date 1003b. Area no longer in use? Production areas stabilized? 1003c. Compacted areas have been cross ripped? 1003d. Drilling pit closed? Subsidence over on drill pit? Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700225	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3936514
679700226	Land Application Area viewing north	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3936502

679700227	Land Application Area viewing SSW	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3936503
679700228	Material pile on north end of Land App Area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3936504
679700229	Material pile on north end of Land App Area 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3936505