

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/24/2016
Document Number:
673403544

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>222312</u>	<u>312772</u>	<u>Waldron, Emily</u>	<input type="checkbox"/>	

Overall Inspection:
SATISFACTORY w/ CMT or AR

Operator Information:

OGCC Operator Number: 10528
Name of Operator: ARCH OIL & GAS LLC
Address: 16400 DALLAS PARKWAY SUITE 400
City: DALLAS State: TX Zip: 75248

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Browning, Jeff	940-391-7210	jbrowning@matthewssouthwest.com	All Inspections

Compliance Summary:

QtrQtr: SENE Sec: 14 Twp: 5N Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/01/2015	673401624	SI	PR	ACTION REQUIRED			No
01/27/2014	673400226	PR	PR	ACTION REQUIRED	Fail		No
11/19/2013	673400124	PR	PR	ACTION REQUIRED	Fail		No
03/16/2012	662300330	PR	PR	SATISFACTORY			No
06/27/2011	200323460	PR	PR	ACTION REQUIRED			Yes
10/03/2006	200103243	PR	PR	SATISFACTORY		Pass	No
02/22/1999	500154450	PR	PR			Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222312	WELL	PR	12/01/2014	OW	081-05288	A.P. URIE 2	PR <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: 970-216-9119

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WEEDS	ACTION REQUIRED	Weeds immediately adjacent to wellhead and inside and on tank berm.	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	09/05/2016

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK BATTERY	SATISFACTORY			

Equipment:				
Type: Pump Jack	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action				Date:
Type: Deadman # & Marked	# 4	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action				Date:

Tanks and Berms:				
<input type="checkbox"/> New Tank		Tank ID: _____		
Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	400 BBLS	HEATED STEEL AST	40.385760,-108.136030
S/AR	SATISFACTORY	Comment:		
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Inspector Name: Waldron, Emily

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Corrective Action				Corrective Date
Comment	Propane inside crude oil berm.			

Venting:

Yes/No	NO
Comment	

Flaring:

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date:

Predrill

Location ID: 222312

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 222312 Type: WELL API Number: 081-05288 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
Field Parameters:			
Sample Location: _____			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____ Wildlife Protection Devices (fired vessels): _____			

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTORY _____ Corrective Date: _____

Comment: No apparent soil migration; erosion or soil movement.

CA: _____

Pits: NO SURFACE INDICATION OF PIT