

Elk Springs Unit 14-8

Inspection# 673403556

Stained soil inside berm with gravel on top. Hard hat for scale. Photo taken facing west.



Stained soil inside berm with gravel on top. Hard hat for scale. Photo taken facing north.



Stained soil outside berm.
Hard hat for scale. Photo
taken facing west.



Stained soil inside and
outside berm. Hard hat for
scale. Photo taken facing
south.

