

Interim Reclamation Inspection- Follow up



Photo 1. Photo taken from the northwestern location, facing West. Corrective actions have been preformed in response to FIR Document #682400912.

Interim Reclamation Inspection- Follow up



Photo 2. Photo taken from the western location, facing South. Corrective actions have been preformed in response to FIR Document #682400912.