


# Final Reclamation Inspection- Overview



Google Earth aerial imagery taken 6/19/2014 illustrating total disturbance area. Location has not been reclaimed per 1004. Location was not recontoured to surrounding landscape.

# Final Reclamation Inspection



**Photo 1.** Photo taken from location entrance, facing East. Location was not recontoured to surrounding landscape and gravel left behind.

# Final Reclamation Inspection



**Photo 2.** Photo taken from western location, facing North. Location was not recontoured to surrounding landscape.

# Final Reclamation Inspection



**Photo 3.** Photo taken from southern location, facing East. Location was not recontoured to surrounding landscape.

# Final Reclamation Inspection



**Photo 4.** Photo taken from northern location, facing East. Location was not recontoured to surrounding landscape.