

# Reclamation Inspection

08/29/2016

Operator: Kestral Resources Inc.

Location ID: 399960

Washington County, CO

SWNW Section 36 T3S R53W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



08.29.2016 13:01





**Figure 2:** Photo taken from the southeast corner of the pit location, facing east. Photo shows vegetation over the reclamation area.





**Figure 3:** Photo taken from the southeast corner of the pit location, facing northeast. Photo shows vegetation over the reclamation area.





**Figure 4:** Photo taken from the southeast corner of the pit location, facing north. Photo shows vegetation over the reclamation area.





**Figure 5:** Photo taken from the location, facing north. Photo shows vegetation over the reclamation area.





**Figure 6:** Photo taken from the location, facing east. Photo shows vegetation over the reclamation area.





**Figure 7:** Photo taken from the location, facing south. Photo shows vegetation over the reclamation area.





**Figure 8:** Photo taken from the location, facing west. Photo shows vegetation over the reclamation area.