



**Photo#1:** Overview of Location to East.

August 18, 2016

Inspection Photos: North Finn VR & BR Breeze API#107-06206





**Photo#2:** Sign on ground, Debris , Associated lines ,risers on Location.

Inspection Photos: North Finn VR & BR Breeze API#107-06206

August 18, 2016





**Photo#3:** B list Noxious Weed, Canada thistle on Location.

Inspection Photos: North Finn VR & BR Breeze API#107-06206

August 18, 2016