



**Photo#1:** View over Location Center to East; sign propped up by Inspector.



**Photo#2:** Sign on ground, Debris , Associated lines ,risers on Location.

Inspection Photos: North Finn VR & BR Breeze API#107-06189

August 18, 2016



**Photo#3:** B list Noxious Weeds, Canada & Bull thistle on Location.

Inspection Photos: North Finn VR & BR Breeze API#107-06189

August 18, 2016



**Photo#4:** Guy Anchors on Location

Inspection Photos: North Finn VR & BR Breeze API#107-06189

August 18, 2016