

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2016

Document Number:

685301211

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|------------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 213982 | 325092 | St John, William (Cal) | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 31250Name of Operator: FRITZ & DIGMAN INCAddress: PO BOX 70024City: ALBUQUERQUE State: NM Zip: 87197-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------|
| Labowskie, Steve | | steve.labowskie@state.co.us | COGCC |
| Digman, Rebecca | 505-379-8689 | rcdigman@yahoo.com | |

Compliance Summary:Qtr/Qtr: SWSW Sec: 27 Twp: 33N Range: 12W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|------------|----------------|-----------------|
| 12/30/2014 | 667700514 | PR | PR | ACTION REQUIRED | | | No |
| 12/08/2014 | 667700490 | PR | PR | ALLEGED VIOLATION | | | Yes |
| 12/02/2014 | 667700472 | PR | PR | ALLEGED VIOLATION | In Process | | Yes |
| 01/03/2014 | 667700151 | PR | SI | SATISFACTORY | In Process | | No |
| 10/15/2013 | 663401267 | PR | PR | ALLEGED VIOLATION | | | Yes |
| 05/30/2013 | 669400713 | PR | PR | ALLEGED VIOLATION | In Process | | Yes |
| 01/09/2013 | 669400382 | PR | PR | ALLEGED VIOLATION | In Process | | Yes |
| 09/20/2001 | 200020683 | PR | PR | ACTION REQUIRED | | Fail | Yes |
| 08/18/1997 | 500146528 | PR | PR | | | Pass | No |
| 07/15/1996 | 500146527 | PR | PR | | | Pass | No |
| 12/04/1995 | 500146526 | PR | PR | | | Fail | Yes |

Inspector Comment:

Inspection report contains comments. See Facilities Section for additional details.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|-------------------------------------|
| 213982 | WELL | PR | 06/30/2007 | OW | 067-05264 | GRIFFITH, DELLA 1 | PR | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

Inspector Name: St John, William (Cal)

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|--------|------------------------------|---------|-------------------|------|
| Access | SATISFACTORY | | | |

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------------------|------------------------------|---------|-------------------|---------|
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|--|------|--------|-------------------|---------|
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Fencing/:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|--------------|------------------------------|---------------|-------------------|---------|
| PUMP JACK | SATISFACTORY | Panel | | |
| TANK BATTERY | SATISFACTORY | Post and Wire | | |

Equipment:

| | | | |
|---------------------------|------------------|-------------------------------|--------------|
| Type: Flow Line | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | | Date: |
| Type: Deadman # & Marked | # 4 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | | Date: |
| Type: Prime Mover | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | Electric Motor | | |
| Corrective Action | | | Date: |
| Type: Ancillary equipment | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | Electric Service | | |

Inspector Name: St John, William (Cal)

| | | | |
|---------------------------|-----|-------------------------------|--------------|
| Corrective Action | | Date: | |
| Type: Ancillary equipment | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | Wellhead | |
| Corrective Action | | Date: | |
| Type: Pump Jack | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | Date: | |

Tanks and Berms: ☐ New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------------|---|----------|-----------|--------|
| PRODUCED WATER | 1 | 300 BBLS | STEEL AST | , |

| | | | |
|--------------------|--------------|----------|------------------|
| S/AR | SATISFACTORY | Comment: | |
| Corrective Action: | | | Corrective Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | | | |
|-------------------|---|-----------------|--|
| Corrective Action | | Corrective Date | |
| Comment | Small patches of vegetation inside and on containment berms need to be removed to comply with Rule 605.a.(4). | | |

Venting:

| | |
|---------|----|
| Yes/No | NO |
| Comment | |

Flaring:

| | | | |
|--------------------|--|------------------------------|--|
| Type | | Satisfactory/Action Required | |
| Comment: | | | |
| Corrective Action: | | Correct Action Date: | |

Predrill

Location ID: 213982

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 213982 Type: WELL API Number: 067-05264 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Inspector Name: St John, William (Cal)

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

S/A/V: SATISFACTORY

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT