

Customer Printed Name Joan Cox



Integrated Production Services. JOB DATA SHEET

Company FOUNDATION ENERGY MAN/Well Name and No. BASS BOX ELDER INVEST 11-34 Engineer Adam Steerman
County Adams Date 8/24/2016 Ticket No. 7770-0981 Unit No. 7770
District Greeley CO 0928-200 Line Size 0 Line Length 0
Job Time: 8:00 AM Shop Time: 7:00 AM Leave Shop: 6:30 AM Arrive Location: 8:00 AM
Field Hrs. 0:50:00 Standby Hours: 0:00:00 Total Hours 3:35:00 Travel Time Hrs. 2:45:00
Trip Miles 110 Leave Location: 3:45 PM Arrive Shop: 5:00 PM

Notice: Engineer to monitor for stray voltage prior to rig up: Wellhead volts: 0 Rig volts : 0

Were there any equipment or down hole failures? Yes No X If yes explain on Quality Control Analysis Form

Were there any hot shots required? Yes No X If yes explain on Quality Control Analysis Form

Were there any personnel problems? Yes No X If yes explain on Quality Control Analysis Form

Were there any accidents? Yes No X If yes explain on Quality Control Analysis Form

Were there any near misses? Yes No X If yes explain on Quality Control Analysis Form

Well Information

Casing Size 0 Liner Size Tubing Size Drill Pipe Size
Drill Collar Minimum I.D. Fluid Level 0 Deviation
Max. Temp. Max. Pressure

Run Data

RUN INFORMATION

*****REMARKS SECTION*****DESCRIBE RUN DETAILS IN FULL*****

1 Time in 8:40 AM Out 8:50 AM
From Surface To 1250'
Service Squeeze gun (holes@1250')

RIH with Squeeze Gun, Holes @ 1250', POOH
Tagged Top Of Cement @ 1362'

2 Time in 1:15 PM Out 1:25 PM
From Surface To 910'
Service Dump Bailer

RIH with Squeeze Gun, Holes @ 910', POOH
Tagged top of Cement @ 1034'

3 Time in 3:15 PM Out 3:25 PM
From Surface To 720
Service Squeeze gun (holes@720')

RIH with Squeeze Gun, Holes @ 720', POOH
Tagged Top of Cement @ 805'

4 Time in 12:00 AM Out 12:00 AM
From 0 To 0
Service 0

5 Time in 12:00 AM Out 12:00 AM
From 0 To 0
Service 0

6 Time in 12:00 AM Out 12:00 AM
From 0 To 0
Service 0

7 Time in 12:00 AM Out 12:00 AM
From 0 To 0
Service 0

8 Time in Out
From To
Service