



Photo#1: Overview of Location from North Entry

August 16, 2016

Inspection Photos: Sandridge Ex Grizzly 3-32H Loc#436007 VR



Photo#2: Large areas no longer needed for Use or Production; subject of Variance Request.

Inspection Photos: Sandridge Ex Grizzly 3-32H Loc#436007 VR

August 16, 2016



Photo#3: East Slope of East N>S Berm, Vegetation is establishing.

Inspection Photos: Sandridge Ex Grizzly 3-32H Loc#436007 VR

August 16, 2016



Photo#4: West slope of East N>S Berm is Bare of Vegetation.

Inspection Photos: Sandridge Ex Grizzly 3-32H Loc#436007 VR

August 16, 2016



Photo#5: East Slope of West N>S Berm, Vegetation is establishing.

Inspection Photos: Sandridge Ex Grizzly 3-32H Loc#436007 VR

August 16, 2016



Photo#6: West Slope of West N>S Berm is bare of Vegetation.

Inspection Photos: Sandridge Ex Grizzly 3-32H Loc#436007 VR

August 16, 2016