

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2016

Document Number:

685500711

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>201804</u>	<u>319897</u>	<u>MONTOYA, JOHN</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10112</u>
Name of Operator:	<u>FOUNDATION ENERGY MANAGEMENT LLC</u>
Address:	<u>16000 DALLAS PARKWAY #875</u>
City:	<u>DALLAS</u> State: <u>TX</u> Zip: <u>75248-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	All Inspections
Condill, J.B.		jbcrog@aol.com	
Espinosa, Bill		billespinosa30@yahoo.com	Inspections

Compliance Summary:

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/31/2014	671102690	PR	SI	SATISFACTORY			No
10/08/2014	671102431	PR	PR	ACTION REQUIRED			No
12/23/2010	200290387	PR	PR	ACTION REQUIRED			Yes
04/16/2010	200242784	PR	SI	ACTION REQUIRED			Yes
02/08/2008	200126442	PR	PR	ACTION REQUIRED			Yes
11/10/2003	200046635	PR	PR	ACTION REQUIRED		Fail	Yes
05/28/2001	1064691	PR	PR	ACTION REQUIRED		Fail	Yes
04/20/1998	500131903	PR	PR			Fail	Yes
10/26/1994	500131897		PR			Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201804	WELL	PR	08/10/2010	GW	001-07208	CHAMPLIN 67 AMOCO E 1	TA <input checked="" type="checkbox"/>

Equipment:

Location Inventory

--

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	ACTION REQUIRED	unused pipe and sucker rod	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "	09/27/2016
WEEDS	ACTION REQUIRED	weeds at wellhead and battery tank inside berms	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "	09/20/2016

Spills:				
Type	Area	Volume	Corrective action	CA Date
Crude Oil	Tank	<= 1 bbl	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "	09/27/2016

Multiple Spills and Releases?

Equipment:				
Type: Deadman # & Marked	# 4	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action				Date:

Venting:	
Yes/No	NO
Comment	

Flaring:	
Type	Satisfactory/Action Required
Comment:	

Corrective Action: _____	Correct Action Date: _____
--------------------------	----------------------------

Predrill

Location ID: 201804
 Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 S/AR: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____
 CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____
 CA: _____ Date: _____
 Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:
 Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:
 Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
 Request LGD Attendance: _____

LGD Contact Information:
 Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 201804 Type: WELL API Number: 001-07208 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 S/A/V: _____ CA Date: _____
 CA: _____
 Comment: _____

Environmental

Spills/Releases:
 Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
what are you going to do with this well	montoyaj	09/06/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685500712	well sign and trash	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3944196
685500713	weeds need controlled	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3944197
685500714	unused equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3944198
685500715	battery sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3944199

Inspector Name: MONTOYA, JOHN

685500716	weeds inside fence area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3944200
685500717	weeds inside berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3944201
685500718	soiled dirt at load line valve	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3944202
685500719	soiled dirt on east side of prod tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3944203