

McIntyre 1-3 ST

Inspection# 673403592

No battery sign. Vegetation growing in berm. No label on buried fiberglass tank.



No labels on buried fiberglass tank.



Stained soil at wellhead.
Tubing stored at wellhead.



Rills coming onto location.
No interim reclamation
apparent.



Rills coming onto location.
No interim reclamation
apparent.



Rills coming onto location.
No interim reclamation
apparent. Noxious weeds
in center of photo.

