

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
09/09/2016
Document Number:
666802557
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>274666</u>	<u>335308</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>100185</u>
Name of Operator:	<u>ENCANA OIL & GAS (USA) INC</u>
Address:	<u>370 17TH ST STE 1700</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Compliance Summary:

QtrQtr:	<u>NWSE</u>	Sec:	<u>26</u>	Twp:	<u>6S</u>	Range:	<u>93W</u>
---------	-------------	------	-----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/23/2015	666801471	PR	PR	SATISFACTORY			No
09/30/2014	666800109	PR	PR	SATISFACTORY			No
02/14/2011	200296396	PR	PR	SATISFACTORY			No
02/14/2011	200296395	PR	PR	SATISFACTORY			No
02/17/2006	200087516	PR	PD	ACTION REQUIRED	In Process	Fail	Yes

Inspector Comment:

Inspection is for Bradenhead test

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
270232	WELL	PR	03/11/2004	GW	045-09498	BENZEL 26-7C (J26NW)	PR	<input checked="" type="checkbox"/>
270233	WELL	PR	03/20/2004	GW	045-09497	BENZEL 26-10B (J26NW)	PR	<input checked="" type="checkbox"/>
274664	WELL	PR	08/13/2005	GW	045-13374	GMU 26-14B (J26NW)	PR	<input checked="" type="checkbox"/>
274665	WELL	PR	08/02/2005	GW	045-13373	GMU 26-12A (J26NW)	PR	<input checked="" type="checkbox"/>
274666	WELL	PR	08/06/2005	GW	045-13372	GMU 26-11C (J26NW)	PR	<input checked="" type="checkbox"/>
274667	WELL	PR	08/11/2005	GW	045-13371	GMU 26-14A (J26NW)	PR	<input checked="" type="checkbox"/>
274668	WELL	PR	07/31/2005	GW	045-13370	GMU 26-5D (J26NW)	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Inspector Name: Murray, Richard

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	AIRS ID 045-0846-001		

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

Type: Plunger Lift	# 7	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Emission Control Device	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Vertical Heated Separator	# 7	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:

Tanks and Berms:

New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	500 BBLS	STEEL AST	39.494940,-107.742403
S/AR	SATISFACTORY	Comment:		
Corrective Action:				Corrective Date:

Paint

Condition Adequate

Other (Content) _____

Inspector Name: Murray, Richard

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action	_____	Corrective Date	_____
-------------------	-------	-----------------	-------

Comment	_____
---------	-------

Venting:

Yes/No	NO
--------	----

Comment	_____
---------	-------

Flaring:

Type	_____	Satisfactory/Action Required	_____
------	-------	------------------------------	-------

Comment:	_____
----------	-------

Corrective Action:	_____	Correct Action Date:	_____
--------------------	-------	----------------------	-------

Predrill

Location ID: 274666

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 270232 Type: WELL API Number: 045-09498 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 270233 Type: WELL API Number: 045-09497 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 274664 Type: WELL API Number: 045-13374 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 274665 Type: WELL API Number: 045-13373 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 274666 Type: WELL API Number: 045-13372 Status: PR Insp. Status: PR

BradenHead

Comment: **Form 17 filled out by operator and signed by COGCC staff**

CA: _____

CA Date: _____

Facility ID: 274667 Type: WELL API Number: 045-13371 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 274668 Type: WELL API Number: 045-13370 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): Y

Comment: _____

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Inspector Name: Murray, Richard

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Gravel	Pass			
Gravel	Pass					
		Ditches	Pass			
Berms	Pass					
Retention Ponds	Pass					

S/A/V: SATISFACTORY Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT