

HALLIBURTON

iCem[®] Service

SYNERGY RESOURCES CORPORATION

Date: Tuesday, November 17, 2015

SRC Vista 44-2N-A

Surface

Job Date: Saturday, November 07, 2015

Sincerely,

Justin Lansdale

Legal Notice

Warning Disclaimer

Although the information contained in this report is based on sound engineering practices, the copyright owner(s) does (do) not accept any responsibility whatsoever, in negligence or otherwise, for any loss or damage arising from the possession or use of the report whether in terms of correctness or otherwise. The application, therefore, by the user of this report or any part thereof, is solely at the user's own risk.

Limitations of Liability

Except as expressly set forth herein, there are no representations or warranties by Halliburton, express or implied, including implied warranties of merchantability and/or fitness for a particular purpose. In no event will Halliburton or its suppliers be liable for consequential, incidental, special, punitive or exemplary damages (including, without limitation, loss of data, profits, use of hardware, or software). Customer accepts full responsibility for any investment made based on results from the Software. Any interpretations, analyses or modeling of any data, including, but not limited to Customer data, and any recommendation or decisions based upon such interpretations, analyses or modeling are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and assumptions are not infallible, and with respect to which professional may differ. Accordingly, Halliburton cannot and does not warrant the accuracy, correctness or completeness of any such interpretation, recommendation, modeling or other products of the Software Product. As such, any interpretation, recommendation or modeling resulting from the Software for the purpose of any drilling, well treatment, production or financial decision will be at the sole risk of Customer. Under no circumstances will Halliburton or its suppliers be liable for any damages.

Table of Contents

1.0 Cementing Job Summary 4

 1.1 Executive Summary4

2.0 Real-Time Job Summary 7

 2.1 Job Event Log7

 2.2 Custom Graph.....9

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **SRC Vista 44-2N-A** cement **Surface** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton [Fort Lupton]

HALLIBURTON

Cementing Job Summary

The Road to Excellence Starts with Safety

Sold To #: 359915		Ship To #: 3700825		Quote #:		Sales Order #: 0902875398	
Customer: SYNERGY RESOURCES CORPORATION				Customer Rep: SEAN			
Well Name: SRC VISTA		Well #: 44-2N-A		API/UWI #: 05-123-41055		State: COLORADO	
Field:		City (SAP): JOHNSTOWN		County/Parish: WELD			
Legal Description:				Rig/Platform Name/Num: ENSIGN 131			
Contractor: ENSIGN DRLG				Job BOM: 7521			
Well Type: GAS				Sales Person: HALAMERICA\HX37727			
				Srv Supervisor: Joseph Scileppi			
Job							

Formation Name			
Formation Depth (MD)	Top	0	Bottom
Form Type			BHST
Job depth MD	652ft		Job Depth TVD
Water Depth			652
Perforation Depth (MD)	From		Wk Ht Above Floor
			To

Well Data										
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing		9.625	8.921	36						
Open Hole Section			13.5				0	639		0
							0	652		0

Tools and Accessories									
Type	Size in	Qty	Make	Depth ft	Type	Size in	Qty	Make	
Guide Shoe	9.625			639	Top Plug	9.625	1	HES	
Float Shoe	9.625				Bottom Plug	9.625		HES	
Float Collar	9.625				SSR plug set	9.625		HES	
Insert Float	9.625				Plug Container	9.625	1	HES	
Stage Tool	9.625				Centralizers	9.625		HES	

Miscellaneous Materials									
Gelling Agt		Conc		Surfactant		Conc	Acid Type		Qty
Treatment Fld		Conc		Inhibitor		Conc	Sand Type		Size
									Qty

Fluid Data									
Stage/Plug #: 1									
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft ³ /sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	Mud Flush III (Powder)	Mud Flush III	20	bbl	8.4				
42 gal/bbl		FRESH WATER							

HALLIBURTON

Cementing Job Summary

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	SwiftCem B2	SWIFTCM (TM) SYSTEM	215	sack	13.4	1.79		4	9.5
9.50 Gal		FRESH WATER							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	Displacement	Displacement	47	bbl	8.33				
Cement Left In Pipe		Amount	32 ft	Reason				Shoe Joint	
Mix Water:		pH ##	Mix Water: ## ppm		Mix Water Temperature: ## °F °C				
			Chloride:						
Cement Temperature: ## °F °C		Plug Displaced by: ## lb/gal kg/m3 XXXX				Disp. Temperature: ## °F °C			
Plug Bumped? Yes/No		Bump Pressure: #### psi MPa				Floats Held? Yes/No			
Cement Returns: ## bbl m3		Returns Density: ## lb/gal kg/m3				Returns Temperature: ## °F °C			
Comment GOT 6 BBLS OF CMT BACK TO SURFACE									

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	Comments
Event	1	Call Out	Call Out	11/7/2015	05:00:00	USER	CREW CALLED OUT FOR ON LOCATION AT 1000
Event	2	Crew Leave Yard	Crew Leave Yard	11/7/2015	08:00:00	USER	
Event	3	Arrive At Loc	Arrive At Loc	11/7/2015	09:00:00	USER	UPON ARRIVAL RIG JUST STARTED RUNNING CASING, MET W/ COMPANY REP TO DISCUSS JOB PROCEDURES
Event	4	Rig-up Lines	Rig-up Lines	11/7/2015	10:00:00	USER	PRE RIG UP JSA W/ CREW
Event	5	Safety Meeting - Pre Job	Safety Meeting - Pre Job	11/7/2015	11:40:00	USER	JSA W/ ALL INVOLVED PERSONNEL
Event	6	Start Job	Start Job	11/7/2015	11:59:46	COM5	
Event	7	Test Lines	Test Lines	11/7/2015	12:02:01	COM5	TESTED LINES TO 2500 PSI, NO VISIBLE LEAKS
Event	8	Pump Spacer 1	Pump Spacer 1	11/7/2015	12:07:05	COM5	PUMPED 5 BBLS OF DYE WATER AT 2.5 BPM AND 2 PSI
Event	9	Pump Spacer 2	Pump Spacer 2	11/7/2015	12:09:37	COM5	PUMPED 20 BBLS OF MUD FLUSH AT 2.7 BPM AND 3 PSI
Event	10	Pump Lead Cement	Pump Lead Cement	11/7/2015	12:17:33	COM5	PUMPED 215 SKS OR 68.5 BBLS OF 13.4 CMT AT 6 BPM AND 46 PSI
Event	11	Check Weight	Check weight	11/7/2015	12:20:59	COM5	WEIGHT VERIFIED W/ SCALES
Event	12	Check Weight	Check weight	11/7/2015	12:26:24	COM5	WEIGHT VERIFIED W/ SCALES

Event	13	Check Weight	Check weight	11/7/2015	12:28:24	COM5	WEIGHT VERIFIED W/ SCALES
Event	14	Shutdown	Shutdown	11/7/2015	12:32:19	COM5	
Event	15	Drop Top Plug	Drop Top Plug	11/7/2015	12:32:32	COM5	PLUG PRE LOADED AND WITNESSED BY COMPANY REP
Event	16	Pump Displacement	Pump Displacement	11/7/2015	12:32:38	COM5	PUMPED 47 BBLS OF H2O AT 3.5 BPM AND 82 PSI, GOT 6 BBLS OF CMT BACK TO SURFACE
Event	17	Bump Plug	Bump Plug	11/7/2015	12:51:29	COM5	145 PSI WAS FINAL CIRCULATING PRESSURE AND LANDED AT 565 PSI
Event	18	Other	Other	11/7/2015	12:56:00	COM5	FLOATS HELD, GOT .5 BBLS BACK TO TRUCK
Event	19	End Job	End Job	11/7/2015	13:01:43	COM5	

2.2 Custom Graph

