



photo 1: Facing east toward the location.



photo 2: Facing northeast toward the location.



photo 3: There is List B noxious weeds (Diffuse knapweed) found growing throughout the location.



photo 4: Center of the location facing east. Vegetation has not established at the location.



photo 5: Facing west along the fill slope.



photo 6: There is plastic netting that remains along the fill slope.



photo 7: The fill slope is not adequately stabilized with vegetation and there are signs of erosion.



photo 8: The fill slope is not adequately stabilized with vegetation and there are signs of erosion.



photo 9: Northwest side of the location facing northeast.



photo 10: Northwest side of the location facing southeast.



photo 11: There are signs of erosion along west side of the pad.



photo 12: Facing toward the nearby undisturbed reference area.