

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/01/2016

Document Number:

673503723

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	256984	324540	COSTA, RYAN	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 8667Name of Operator: PETROGLYPH ENERGY INCAddress: 960 BROADWAY AVE SUITE 500City: BOISE State: ID Zip: 83706

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
JUDGE BEAU		bjudge@pgei.com	
POWELL PAUL		ppowell@pgei.com	
COLBY NICOLE		ncolby@pgei.com	
HACKNEY MIKE		mhackney@petroglyph.com	

Compliance Summary:QtrQtr: SWNE Sec: 36 Twp: 28S Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/15/2011	659400027	PA	PA	ACTION REQUIRED		Fail	No
09/30/2011	200324195	SR	PA	ACTION REQUIRED	In Process	Pass	No
09/23/2011	200323106	PR	PA	SATISFACTORY	In Process	Pass	No
07/22/2011	200319761	PR	SI	SATISFACTORY			No
05/18/2011	200311997	PR	SI	SATISFACTORY			No
01/25/2011	200295626	PR	SI	SATISFACTORY			No
03/26/2010	200239865	PR	SI	SATISFACTORY			No
02/13/2009	200203856	ES	SI	SATISFACTORY			No
09/29/2008	200196507	PR	SI	SATISFACTORY			No
06/20/2007	200113951	PR	PR	SATISFACTORY		Pass	No
01/19/2006	200083299	PR	PR	SATISFACTORY		Pass	No
03/03/2003	200035733	PR	PR	SATISFACTORY		Pass	No
10/25/2001	200021056	DG	DG	SATISFACTORY	Fail	Pass	No

Inspector Comment:Reclamation Inspection**Related Facilities:**

Inspector Name: COSTA, RYAN

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
256984	WELL	PA	08/31/2011	GW	055-06221	STATE 9W	RI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 256984

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 256984 Type: WELL API Number: 055-06221 Status: PA Insp. Status: RI

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Inspector Name: COSTA, RYAN

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass

Pit mouse/rat holes, cellars backfilled Pass

Debris removed Fail

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% Fail

Cropland: perennial forage _____

Weeds present Fail

Subsidence _____

Comment:

The vegetation has not established and there are noxious weeds (Diffuse knapweed) growing along the access road. There was piles of straw debris at the west side of the location and plastic debris along the southeast side. See Attached Photos

Corrective Action:

Remove and control noxious weed growth. Remove plastic debris and piles of straw debris. Reseed and stabilize areas of the location to facilitate vegetation establishment.

Date

11/30/2016

Overall Final Reclamation Fail

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: ACTION REQUIRED

Corrective Date: 10/14/2016

Comment: There are signs of erosion occurring along the access road. There is also signs of erosion at the southeast and south side of the location. See Attached Photos

CA: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
The noxious weeds (Diffuse knapweed) have developed seed. These plants will need to be collected and removed to prevent further seed dispersal. Other control methods will need to be utilized and continued efforts must be performed to adequately control the noxious weed infestation.	CostaR	09/13/2016
Establish vegetation with total perennial non-invasive plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture that matches the adjacent pastureland or a seed mixture requested by the landowner. Continue to monitor and manage this site until the final reclamation requirements are achieved.	CostaR	09/13/2016
Submit Form 4 when corrective actions are completed. Include photographs or other documentation showing completion of corrective actions required in this inspection.	CostaR	09/13/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673503724	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3949672