



Photo 1. View of the project area from the southeastern corner facing center. One well on location. Unused equipment and vehicle are being stored on location.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Revegetation is progressing with crested wheatgrass (*Agropyron cristatum*), snakeweed (*Gutierrezia sarothrae*), and western wheatgrass (*Pascopyrum smithii*).





Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward.