

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2016

Submitted Date:

09/15/2016

Document Number:

685500845

**FIELD INSPECTION FORM**

Loc ID 330188 Inspector Name: MONTOYA, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 10 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
REDDY, LUKE		Luke.Reddy@anadarko.com	<a href="#">ALL INSPECTIONS</a>
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	EMERGENCY CONTACT NUMBER OK		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	ROD IRON FENCE SE CORNER N40.19452 W-104.35041		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	SE CORNER N40.19450 W-104.35068		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	BARBWIRE FENCE		

Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	SE CORNER N40.19450 W-104.35068		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	SE CORNER N40.19450 W-104.35068		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.194210,-104.350410
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		,
Comment:	75 BBL CAPACITY WATER TANK				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? P

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass	Gravel	Pass			
Comment: <input type="text"/> Corrective Action: <input type="text"/> Date: _____						
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
INTERMITTER CONTROLLER ON WELLHEAD, SATISFACTORY	montoyaj	09/15/2016