

Margaret Spaulding 2

Inspection# 673403610

Wellhead sign removed.
Stained soil and free product
at wellhead.



Stained soil evidence of
stormwater transport of
product.

