



Photo#1 :Overview of Location; site has not been re-contoured or vegetated. Kochia is the dominate species of Vegetation.

September 3, 2016

Inspection Photos: Black Hills PA Ute 4-17 API#077-08242



Photo#2: View of Cut Slope.

Inspection Photos: Black Hills PA Ute 4-17 API#077-08242

September 3, 2016



Photo#3: Location has not been de-compacted or had gravel removed.

Inspection Photos: Black Hills PA Ute 4-17 API#077-08242

September 3, 2016



Photo#4: Debris on Location .

Inspection Photos: Black Hills PA Ute 4-17 API#077-08242

September 3, 2016