



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Continue weed control.		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Dehydrator	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES		
Comment:	Bradens are open to vent.		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>262339</u>	Type:	<u>WELL</u>	API Number:	<u>045-08016</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>282744</u>	Type:	<u>WELL</u>	API Number:	<u>045-11819</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>282745</u>	Type:	<u>WELL</u>	API Number:	<u>045-11820</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>282746</u>	Type:	<u>WELL</u>	API Number:	<u>045-11821</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>282747</u>	Type:	<u>WELL</u>	API Number:	<u>045-11822</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass					
		Gravel	Pass			
		Ditches	Pass			
		Compaction	Pass			
Seeding	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT