

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/15/2016

Submitted Date:

09/15/2016

Document Number:

674703129**FIELD INSPECTION FORM**

Loc ID 335652	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> <u>22</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener, Garrett		garrett@caerusoilandgas.com	
Janicek, Jake		JJanicek@caerusoilandgas.com	
McKee, Michael		MMckee@caerusoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265443	WELL	PR	05/01/2012	GW	045-09015	CHEVRON 32-7D	PR
265530	WELL	PR	05/01/2012	GW	045-09026	CHEVRON 42-7D	PR
265531	WELL	PR	05/01/2012	GW	045-09025	CHEVRON 43-7D	PR
265532	WELL	PR	05/01/2012	GW	045-09024	CHEVRON 31-7D	PR
265533	WELL	PR	05/01/2012	GW	045-09023	CHEVRON 41-7D	PR
265534	WELL	PR	07/26/2013	GW	045-09022	CHEVRON 33-7D	PR
288551	WELL	PR	09/28/2007	GW	045-13296	CHEVRON 41A-7D	PR
289254	WELL	PR	01/31/2011	GW	045-13708	CHEVRON 41C-7D	PR
289376	WELL	PR	09/28/2007	GW	045-13738	CHEVRON 41D-7D	PR
289422	WELL	PR	09/28/2007	GW	045-13759	CHEVRON 42A-7D	PR
289423	WELL	PR	10/01/2011	GW	045-13758	CHEVRON 31B-7D	PR
289424	WELL	PR	09/28/2007	GW	045-13757	CHEVRON 43B-7D	PR
289425	WELL	PR	09/28/2007	GW	045-13756	CHEVRON 43D-7D	PR
289426	WELL	PR	09/28/2007	GW	045-13755	CHEVRON 43A-7D	PR
289699	WELL	PR	09/28/2007	GW	045-13851	CHEVRON 42D-7D	PR
289700	WELL	PR	09/28/2007	GW	045-13850	CHEVRON 31D-7D	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 866-580-9382

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		

Comment:	8 on S. west and 8 on N east		Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 16			
Comment:			Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Chemical container at wells		Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	2 - 300 bbl tanks in N.east tank battery			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: 2 - 300 bbl tanks in N.east tank battery				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: 2 - 300 bbl tank in S.West tank battery at entrance of location.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	265443	Type:	WELL	API Number:	045-09015	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265530	Type:	WELL	API Number:	045-09026	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265531	Type:	WELL	API Number:	045-09025	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265532	Type:	WELL	API Number:	045-09024	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265533	Type:	WELL	API Number:	045-09023	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265534	Type:	WELL	API Number:	045-09022	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288551	Type:	WELL	API Number:	045-13296	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	289254	Type:	WELL	API Number:	045-13708	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 289376	Type: WELL	API Number: 045-13738	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289422	Type: WELL	API Number: 045-13759	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289423	Type: WELL	API Number: 045-13758	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289424	Type: WELL	API Number: 045-13757	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289425	Type: WELL	API Number: 045-13756	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289426	Type: WELL	API Number: 045-13755	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289699	Type: WELL	API Number: 045-13851	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289700	Type: WELL	API Number: 045-13850	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

--

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed?   P  

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite?   Pass  

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed?   Pass  

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked?   Pass  

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
				Material Handling And Spill Prevention	Pass	
Berms	Pass					
Seeding	Pass					
		Gravel	Pass			
		Ditches	Pass			
		Compaction	Pass			
Gravel	Pass					
Compaction	Pass					
Ditches	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**    ☒ NO SURFACE INDICATION OF PIT