

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2016

Submitted Date:

09/16/2016

Document Number:

675203286**FIELD INSPECTION FORM**Loc ID 323867 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	<a href="#">All Inspections</a>
Giboo, David	(970) 319-2211	dgiboo@blm.com	<a href="#">Lead Petroleum Engineering Tech</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211042	WELL	PR	12/25/2002	GW	045-06800	GASAWAY FED 6205	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Satisfactory		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Satisfactory		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate



Inspected Facilities									
Facility ID:	211042	Type:	WELL	API Number:	045-06800	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT