

Inspector Name: Colby, Lou

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2016

Document Number:

680101100

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	312666	312666	Colby, Lou	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		wbankert@laramie-energy.com	
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	Enviro Pice/Laramie

Compliance Summary:QtrQtr: NWNE Sec: 12 Twp: 9S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/16/2015	675202031			ACTION REQUIRED			No

Inspector Comment:

This is an Interim Reclamation and Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
259130	WELL	PR	03/12/2015	GW	077-08721	BUZZARD CREEK 12-2	RI	<input checked="" type="checkbox"/>
417028	WELL	PR	09/12/2014	GW	077-10085	NVega Fed 12B 6-14D	RI	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: <u>1</u>	Drilling Pits: <u>1</u>	Wells: <u>2</u>	Production Pits: <u> </u>
Condensate Tanks: <u>2</u>	Water Tanks: <u>2</u>	Separators: <u>2</u>	Electric Motors: <u> </u>
Gas or Diesel Mortors: <u> </u>	Cavity Pumps: <u> </u>	LACT Unit: <u> </u>	Pump Jacks: <u> </u>
Electric Generators: <u> </u>	Gas Pipeline: <u>1</u>	Oil Pipeline: <u>1</u>	Water Pipeline: <u> </u>
Gas Compressors: <u> </u>	VOC Combustor: <u>1</u>	Oil Tanks: <u> </u>	Dehydrator Units: <u> </u>
Multi-Well Pits: <u> </u>	Pigging Station: <u> </u>	Flare: <u> </u>	Fuel Tanks: <u> </u>

LocationEmergency Contact Number (S/AR): Corrective Date:

Inspector Name: Colby, Lou

Comment:

Corrective Action:

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No

Comment

Flaring:

Type

Satisfactory/Action Required

Comment:

Corrective Action:

Correct Action
Date:

Predrill

Location ID: 312666

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
Agency	yokleyb	Operator must implement best management practices to contain any unintentional release of fluids.	05/03/2010
Agency	yokleyb	Location is in a sensitive area because of proximity to a domestic water well; therefore either a lined drilling pit or closed loop system must be implemented.	05/03/2010
Agency	yokleyb	Location is in a sensitive area because of proximity to a domestic water well; therefore production pits must be lined.	05/03/2010
Agency	yokleyb	The moisture content of any drill cuttings in a cuttings pit, trench, or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts. At the time of closure, the drill cuttings must also meet the applicable standards of table 910-1.	05/03/2010
Agency	yokleyb	Location is in a sensitive area because of proximity to surface water; therefore, operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations.	05/03/2010

S/AR: _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 259130 Type: WELL API Number: 077-08721 Status: PR Insp. Status: RI

Inspector Name: Colby, Lou

Facility ID: 417028 Type: WELL API Number: 077-10085 Status: PR Insp. Status: RI

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:
Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment:

1003a. Waste and Debris removed? Pass

CM
CA CA Date

Unused or unneeded equipment onsite? Pass

CM
CA CA Date

Pit, cellars, rat holes and other bores closed? Pass

CM
CA CA Date

Guy line anchors marked?

CM
CA CA Date

1003b. Area no longer in use? In Production areas stabilized? In

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Inspector Name: Colby, Lou

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? In

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured Pass

80% Revegetation In

1003 f. Weeds Noxious weeds? I

Comment: **Small Population of Canada Thistle, B List Noxious Weed was noted on Location; advised to Monitor closely & Control. Refer to SW Section for concerns of Cut Slope sloughing & erosion which is affecting vegetation.**

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					
Compaction	Pass					
Seeding						
Ditches	Fail					on top of Cut Slope
Mulching	Pass					

S/A/V: **ACTION REQUIRED**

Corrective Date: **10/31/2016**

Comment: **SW is eroding/saturating Cut slope, washing out vegetation; sediment is migrating on to Location.**

CA: **Install / maintain appropriate BMPs to control SW saturation / erosion of Cut Slope.**

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101124	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3954035