

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2016

Submitted Date:

09/19/2016

Document Number:

675203289

FIELD INSPECTION FORM

Loc ID 324233 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268056	WELL	PR	09/14/2006	GW	045-09241	GASAWAY 6233	PR

General Comment:

(This area is currently blank for general comments.)

Location					
Lease Road:					
	Type	Access			
	comment:	Satisfactory			
	Corrective Action:				Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
	Type	WELLHEAD			
	Comment:	Satisfactory			
	Corrective Action:				Date:
	Type	TANK LABELS/PLACARDS			
	Comment:	Satisfactory			
	Corrective Action:				Date:
Emergency Contact Number:					
	Comment:	<input style="width: 100%;" type="text"/>			
	Corrective Action:	<input style="width: 100%;" type="text"/>			
					Date: _____
Good Housekeeping:					
	Type	STORAGE OF SUPL			
	Comment:	Trailer parked on location			
	Corrective Action:				Date:
Overall Good: <input type="checkbox"/>					
Spills:					
	Type	Area	Volume		
In Containment: No					
	Comment:	<input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
	Type	WELLHEAD			
	Comment:				
	Corrective Action:				Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tanak ID	SE GPS	
METHANOL	1	<50 BBLs	STEEL AST			
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities

Facility ID: 268056 Type: WELL API Number: 045-09241 Status: PR Insp. Status: PR

Producing Well

Comment: [PR w/ Plunger](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT