

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2016

Submitted Date:

09/19/2016

Document Number:

675203290

FIELD INSPECTION FORM

Loc ID 322471 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210576	WELL	PR	01/22/2013	GW	045-06332	GASAWAY (SHEFFIELD) 6209 (1-17)	TA

General Comment:

Location

Lease Road:

Type	Access				
comment:	Satisfactory				
Corrective Action:				Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD				
Comment:	Satisfactory				
Corrective Action:				Date:	
Type	TANK LABELS/PLACARDS				
Comment:	Satisfactory				
Corrective Action:				Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK				
Comment:					
Corrective Action:				Date:	
Type	SEPARATOR				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	1	400 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Same						
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:				Date:		

Inspected Facilities

Facility ID: 210576 Type: WELL API Number: 045-06332 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT