

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/16/2016

Submitted Date:

09/19/2016

Document Number:

666802579**FIELD INSPECTION FORM**

Loc ID 334720 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263903	WELL	PR	07/23/2007	GW	045-08154	BERNKLAU RWF 13-4	PR
263906	WELL	PR	12/18/2002	GW	045-08157	BERNKLAU RWF 314-4	PR
263907	WELL	PR	12/26/2002	GW	045-08158	BERNKLAU RWF 313-4	PR
286778	WELL	PR	09/15/2006	GW	045-12776	DIAMOND ELK RWF 343-5	PR
286779	WELL	PR	09/15/2006	GW	045-12775	DIAMOND ELD RWF 414-4	TA
286783	WELL	PR	09/18/2006	GW	045-12774	DIAMOND ELK RWF 413-4	PR

General Comment:

[Inspection is due to mud coming out of Bradenhead causing a reportable spill.](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-2062-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 6		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	1	200 BBLs	STEEL AST		,	
Comment: Centralized battery						
Corrective Action:					Date:	

Paint

Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		39.463809,-107.900034
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	263903	Type:	WELL	API Number:	045-08154	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	263906	Type:	WELL	API Number:	045-08157	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	263907	Type:	WELL	API Number:	045-08158	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	286778	Type:	WELL	API Number:	045-12776	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	286779	Type:	WELL	API Number:	045-12775	Status:	PR	Insp. Status:	TA
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Workover									
Comment:	Workover rig on location to repair casing leak.								
Corrective Action:						Date:			
Facility ID:	286783	Type:	WELL	API Number:	045-12774	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental**Spills/Releases:**

Type of Spill:	_____	Estimated Spill Volume:	_____
Comment:	_____		
Corrective Action:	_____		Date: _____
Reportable:	_____	GPS: Lat _____	Long _____
Proximity to Surface Water:	_____	Depth to Ground Water:	_____

Water Well:

		Lat	Long
DWR Receipt Num:	_____	Owner Name:	_____
		GPS :	_____

Field Parameters:

Sample Location:	_____	Comment:	_____
------------------	-------	----------	-------

Spill/Remediation:

Comment:	_____		
Corrective Action:	_____	Date:	_____

Emission Control Burner (ECB): NO _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): YES _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Gravel	Pass			
Compaction	Pass					
		Ditches	Pass			
Seeding	Pass					
Culverts	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT