

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2016

Document Number:

680101118

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	299523	334429	Colby, Lou	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED☒ INSPECTOR REQUESTS FORM 42 WHEN
CORRECTIVE ACTIONS ARE COMPLETED**Contact Information:**

Contact Name	Phone	Email	Comment
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	Enviro Pice/Laramie
		wbankert@laramie-energy.com	

Compliance Summary:QtrQtr: SENE Sec: 4 Twp: 10S Range: 93W**Inspector Comment:**

This is an Abandoned Location Inspection for Wells API#s 077-09562, 09563, 09564, 09565, 09566, 09780, 09781, 09782, 09783, 09784, 09785, 09786, 09808, 09809, 09810, 09811. APDs first approved in 2008 for Delta Petroleum; Abandoned 5/18/2016 by Laramie Energy.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
295224	WELL	AL	05/18/2016	LO	077-09562	Vega Unit 33-444	RI	<input checked="" type="checkbox"/>
295225	WELL	AL	05/18/2016	LO	077-09563	Vega 4-424	RI	<input checked="" type="checkbox"/>
295226	WELL	AL	05/18/2016	LO	077-09564	Vega 4-411	RI	<input checked="" type="checkbox"/>
295227	WELL	AL	05/18/2016	LO	077-09565	Vega 4-414	RI	<input checked="" type="checkbox"/>
295229	WELL	AL	05/18/2016	LO	077-09566	Vega 4-421	RI	<input checked="" type="checkbox"/>
299141	WELL	AL	05/18/2016	LO	077-09780	Vega 4-312	RI	<input checked="" type="checkbox"/>
299142	WELL	AL	05/18/2016	LO	077-09781	Vega 4-314	RI	<input checked="" type="checkbox"/>
299143	WELL	AL	05/18/2016	LO	077-09782	Vega 4-311	RI	<input checked="" type="checkbox"/>
299144	WELL	AL	05/19/2016	LO	077-09783	Vega 4-322	RI	<input checked="" type="checkbox"/>
299145	WELL	AL	05/19/2016	LO	077-09784	Vega 4-321	RI	<input checked="" type="checkbox"/>

Inspector Name: Colby, Lou

299146	WELL	AL	05/19/2016	LO	077-09785	Vega 4-412	RI	<input checked="" type="checkbox"/>
299147	WELL	AL	05/19/2016	LO	077-09786	Vega 4-313	RI	<input checked="" type="checkbox"/>
299520	WELL	AL	05/18/2016	LO	077-09808	Vega Unit 33-442	RI	<input checked="" type="checkbox"/>
299521	WELL	AL	05/18/2016	LO	077-09809	Vega Unit 33-443	RI	<input checked="" type="checkbox"/>
299522	WELL	AL	05/18/2016	LO	077-09810	Vega 4-422	RI	<input checked="" type="checkbox"/>
299523	WELL	AL	05/18/2016	LO	077-09811	Vega 4-413	RI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	_____
Comment	_____

Flaring:

Type	_____	Satisfactory/Action Required	_____
Comment:	_____		
Corrective Action:	_____	Correct Action Date:	_____

Predrill

Location ID: 299523

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 295224 Type: WELL API Number: 077-09562 Status: AL Insp. Status: RI

Facility ID: 295225 Type: WELL API Number: 077-09563 Status: AL Insp. Status: RI

Facility ID: 295226 Type: WELL API Number: 077-09564 Status: AL Insp. Status: RI

Facility ID: 295227 Type: WELL API Number: 077-09565 Status: AL Insp. Status: RI

Facility ID: 295229 Type: WELL API Number: 077-09566 Status: AL Insp. Status: RI

Facility ID: 299141 Type: WELL API Number: 077-09780 Status: AL Insp. Status: RI

Facility ID: 299142 Type: WELL API Number: 077-09781 Status: AL Insp. Status: RI

Facility ID: 299143	Type: WELL	API Number: 077-09782	Status: AL	Insp. Status: RI
Facility ID: 299144	Type: WELL	API Number: 077-09783	Status: AL	Insp. Status: RI
Facility ID: 299145	Type: WELL	API Number: 077-09784	Status: AL	Insp. Status: RI
Facility ID: 299146	Type: WELL	API Number: 077-09785	Status: AL	Insp. Status: RI
Facility ID: 299147	Type: WELL	API Number: 077-09786	Status: AL	Insp. Status: RI
Facility ID: 299520	Type: WELL	API Number: 077-09808	Status: AL	Insp. Status: RI
Facility ID: 299521	Type: WELL	API Number: 077-09809	Status: AL	Insp. Status: RI
Facility ID: 299522	Type: WELL	API Number: 077-09810	Status: AL	Insp. Status: RI
Facility ID: 299523	Type: WELL	API Number: 077-09811	Status: AL	Insp. Status: RI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

Inspector Name: Colby, Lou

CM _____
CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____
CA _____ CA Date _____

Guy line anchors marked? _____

CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: **Range Land**

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed **Fail**

Gravel removed **Fail**

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage _____

Weeds present **Pass** Subsidence **Pass**

Comment: **APDs have not been drilled, Permits were Abandoned 5/18/2016. No Wells were observed. Location was constructed and needs Final Reclamation. 2A for this Location could not be found in COGCC Files.**

Inspector Name: Colby, Lou

Corrective Action:

Reclaim Location. Perform Final Reclamation per COGCC 1004 Rules. Reclamation Activities to be complete by June 15, 20162017. Refer to Photos attached for detail of Site Conditions.

Date

Overall Final Reclamation

Fail

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTORY

Corrective Date:

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101118	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3956662
680101134	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3956660