

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2016

Submitted Date:

09/19/2016

Document Number:

674703138**FIELD INSPECTION FORM**
 Loc ID 335774 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone | Email                        | Comment |
|------------------|-------|------------------------------|---------|
| Janicek, Jake    |       | JJanicek@caerusoilandgas.com |         |
| Elsener, Garrett |       | garrett@caerusoilandgas.com  |         |
| McKee, Michael   |       | MMckee@caerusoilandgas.com   |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 269990      | WELL | PR     | 12/30/2004  | GW         | 045-09435 | CHEVRON/TEXACO 24C-12D | PR          |
| 270032      | WELL | PR     | 12/30/2004  | GW         | 045-09439 | CHEVRON/TEXACO 34C-12D | PR          |
| 270033      | WELL | PR     | 12/30/2004  | GW         | 045-09440 | CHEVRON/TEXACO 31C-13D | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 866-580-9382

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                       |     |       |                 |
|-----------------------|-----|-------|-----------------|
| <b>Equipment:</b>     |     |       | corrective date |
| Type: Plunger Lift    | # 3 |       |                 |
| Comment:              |     |       |                 |
| Corrective Action:    |     | Date: |                 |
| Type: Bird Protectors | # 3 |       |                 |
| Comment:              |     |       |                 |
| Corrective Action:    |     | Date: |                 |
| Type: Gathering Line  | # 3 |       |                 |

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Tanks and Berms:**

|                    |   |          |           |          |        |       |
|--------------------|---|----------|-----------|----------|--------|-------|
| Contents           | # | Capacity | Type      | Tanak ID | SE GPS |       |
| CONDENSATE         | 1 | 300 BBLs | STEEL AST |          | ,      |       |
| Comment:           |   |          |           |          |        |       |
| Corrective Action: |   |          |           |          |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 269990 Type: WELL API Number: 045-09435 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 270032 Type: WELL API Number: 045-09439 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 270033 Type: WELL API Number: 045-09440 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            | Pass            |                         |                       |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |
| Seeding          | Pass            |                         |                       |               |                          |         |
| Compaction       | Pass            |                         |                       |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |
|                  |                 | Culverts                | Pass                  |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
|                  |                 | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT