

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2016

Submitted Date:

09/19/2016

Document Number:

674703141

**FIELD INSPECTION FORM**

Loc ID 335463 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 12 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
McKee, Michael		MMckee@caerusoilandgas.com	
Elsener, Garrett		garrett@caerusoilandgas.com	
Janicek, Jake		JJanicek@caerusoilandgas.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286500	WELL	PR	05/01/2009	GW	045-12686	PUCKETT 31A-24D	PR
286516	WELL	PR	05/01/2009	GW	045-12693	PUCKETT 42A-24D	PR
286517	WELL	PR	05/01/2009	GW	045-12692	PUCKETT 41C-24D	PR
286519	WELL	PR	06/01/2009	GW	045-12691	PUCKETT 41B-24D	PR
286522	WELL	PA	11/27/2008	GW	045-12690	PUCKETT 41A-24D	PR
286523	WELL	PR	10/01/2011	GW	045-12687	PUCKETT 31B-24D	PR
286530	WELL	PR	01/01/2011	GW	045-12689	PUCKETT 31C-24D	PR
290865	WELL	PR	06/01/2009	GW	045-14209	PUCKETT 41D-24D	PR
290866	WELL	PR	02/28/2010	GW	045-14208	PUCKETT 31D-24D	PR

**General Comment:**

Puckett 41A-24D well is Producing not Plugged & Abandoned. Well status needs to be changed to "PR"

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 2		corrective date
Comment:	Chemical container at wells and tank battery.		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		

Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gallons	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	200 BBLs	PBV STEEL		,
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	286500	Type:	WELL	API Number:	045-12686	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	286516	Type:	WELL	API Number:	045-12693	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	286517	Type:	WELL	API Number:	045-12692	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	286519	Type:	WELL	API Number:	045-12691	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	286522	Type:	WELL	API Number:	045-12690	Status:	PA	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well status showing PA. Well is producing and has recent production records.								
Corrective Action:					Date:				
Facility ID:	286523	Type:	WELL	API Number:	045-12687	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	286530	Type:	WELL	API Number:	045-12689	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	290865	Type:	WELL	API Number:	045-14209	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 290866 Type: WELL API Number: 045-14208 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed?  P

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite?  Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed?  Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked?  Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Gravel	Pass			
		Ditches	Pass			
Compaction	Pass					
Ditches	Pass					
Seeding	Pass					
				Material Handling And Spill Prevention	Pass	
Gravel	Pass					
Check Dams	Pass					
Berms	Pass					
		Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT