

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Post and Hog Wire		
Corrective Action:		Date:	
Equipment:			
Type: Compressor	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry Equipment		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Domestic Tap - Not in Use		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Sound Walls		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Lube Oil Tank on Spill Prevention		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
OTHER	1	OTHER	Open Top		,
Comment:	Steel Mesh Top				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	Used Oil (Compressor Skid) and Produced Water	
Other (Capacity)	30 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 214794 Type: WELL API Number: 067-06398 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT