

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/20/2016

Submitted Date:

09/20/2016

Document Number:

666802582**FIELD INSPECTION FORM**

Loc ID 334907 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256072	WELL	PR	09/14/1999	GW	045-07427	COUEY 8-16 (18E)	PR
258256	WELL	PR	03/31/2000	GW	045-07526	COUEY 8-9 (18E)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

2

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

2

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment: Centralized battery					
Corrective Action:					Date:

Paint

Condition

Other (Content)

Other (Capacity) 500gal

Other (Type)

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tanak ID	SE GPS			
CONDENSATE		1	300 BBLS	STEEL AST			39.458180,-107.684014			
Comment:										

Corrective Action:		Date:		
Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected FacilitiesFacility ID: 256072 Type: WELL API Number: 045-07427 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 258256 Type: WELL API Number: 045-07526 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Seeding	Pass					
		Gravel	Pass			
		Culverts	Pass			
		Ditches	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT