

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2016

Submitted Date:

09/20/2016

Document Number:

673714005**FIELD INSPECTION FORM**
 Loc ID 386901 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 36200Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM COAddress: 3600 S. YOSEMITE ST - STE 900City: DENVER State: CO Zip: 80237-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
gynberg, jack	(303) 850-7490	j.grynpetro@gynberg.com	
Sutphin, Dirk		dirk.sutphin@state.co.us	COGCC Engineer
Edelen, Randy		r.edelen@gynberg.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218009	WELL	DG	09/13/2016	DA	073-05055	Schulte 1-13R	DG

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:	Murfin Rig 25 at CR and gate to location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 719-691-9443

Corrective Action: _____ Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 218009 Type: WELL API Number: 073-05055 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Murfin Rig 25 Pusher/Rig Manager: Ray
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: YES Unlined Pit: YES Closed Loop: NO Semi-Closed Loop: NO
 Multi-Well: NO Disposal Location: onsite

Comment: Drilled through cement at 5' and 100'. Cleaned out to 289', set middle of retrievable bridge plug at 240'. Shoe at 250'. 21' joints. Cutter wireline ran RBL to show cement and caliper logs to show casing thickness on surface casing. Electronic copies sent to COGCC engineer. Pressure test on casing failed before bridge plug was set and after bridge plug was set. No pull test on casing was performed.

Corrective Action: _____ Date: _____

Cement**Cement Contractor**

Contractor Name: Consolidated Contractor Phone: 785-672-8822

Surface Casing

Cement Volume (sx): 115 Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: Class A, 15.8#

Comment: Included 5 sxs each in rat and mouse hole.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: rangeland and cropland**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? _____

Comment

Corrective Action

Date _____

Unused or unneeded equipment onsite? _____

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment

Corrective Action

Date _____

Guy line anchors marked? _____

Comment

Corrective Action

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Ditches	Pass					
Waddles	Pass					
Slope Roughening	Pass					
Blankets	Pass	Other	Pass	Vehicle Tracking	Pass	cattle guard
Berms	Pass	Other	Pass	Material Handling And Spill Prevention	Pass	vegetation

Comment: Four top soil piles were also compacted in addition to pit stock piles and berms. Waddles were staked and trenched. Double berms, ditched and compaction on west side of location.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Drilling Pit Lined: NO Pit ID: _____ Lat: 39.550400 Long: -103.207630

Reference Point: SE Other: _____ Length: 125 Width: 125

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Type: Water Fresh Lined: YES Pit ID: _____ Lat: 39.550060 Long: -103.207300

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Plastic Liner Condition: Adequate

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: LivestockFencing Condition: Adequate

Comment:

Corrective
Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective
Action

Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard:

Comment:

Corrective
Action

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673714005	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3957772
673714007	Grynberg Schulte 1-13R	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3957770