

## Caddis Federal 33-9

Inspection# 673403660

Location overview. Well has been plugged, equipment removed.



Stained soil in battery area.





Stained soil in battery area. Hard hat for scale.



Stained soil in battery area. Hard hat for scale.

