



**Location**

<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective ActionL		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	EMERGENCY NUMBER OK		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	ROD IRON FENCE SE CORNER N40.20127 W-104,35099		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 251557 Type: WELL API Number: 123-19360 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: MIT TEST START 420 PSI, 5 MIN 420 PSI, 10 MIN 420 PSI, 15 MIN 420 PSI, -0 PASSED

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Comment: BRADENHEAD PLUMBED TO SURFACE

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
MIT TEST	montoyaj	09/21/2016