

# Construction Inspection

09/20/2016

Operator: Grynberg

Location ID: 386901

Lincoln County, CO

SWSW Section 3 T6S R52W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



**Figure 1:** Photo taken from the south end of the location, facing east. Location had been expanded ~50 to the south.



**Figure 2:** Photo taken from the northwest corner of the location, facing south. Photo shows straw wattles used as stormwater and sediment control BMPs have been properly entrenched.



**Figure 3:** Photo taken from the northwest corner of the location, facing east. Photo shows straw wattle “j-hook” had been extended and additional surface roughening had been incorporated.



**Figure 4:** Photo taken from the southwest corner of the location. Photo shows topsoil pile. Construction foremen had mentioned they placed additional topsoil at this, and one other location to the southeast when they expanded the location.