

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2016

Submitted Date:

09/22/2016

Document Number:

666802599**FIELD INSPECTION FORM**

Loc ID 334990 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281129	WELL	PR	04/15/2006	GW	045-11402	LAST DANCE 43C-3-792	PR
281130	WELL	PR	02/07/2011	GW	045-11401	LAST DANCE 43A-3-792	PR
281153	WELL	PR	04/10/2006	GW	045-11403	LAST DANCE 33C-3-792	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:	Hooked up to wellheads		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead		
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		39.475116,-107.647581
Comment:	Bradenheads hooked up to tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	4	200 BBLs	STEEL AST		39.476750,-107.647968
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	281129	Type:	WELL	API Number:	045-11402	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281130	Type:	WELL	API Number:	045-11401	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	281153	Type:	WELL	API Number:	045-11403	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Gravel	Pass			
Waddles	Pass					
		Culverts	Pass			
Seeding	Pass					
		Ditches	Pass			
Rip Rap	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT