

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2016

Submitted Date:

09/22/2016

Document Number:

666802598**FIELD INSPECTION FORM**

Loc ID 324247 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269870	WELL	PR	03/31/2004	GW	045-09418	LAST DANCE 9-3	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: [Chemical unit at wellhead](#)

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents

#

Capacity

Type

Tanak ID

SE GPS

CONDENSATE

1

&lt;100 BBLS

PBV STEEL

,

Comment: [Centralized battery](#)

Corrective Action:

Date:

**Paint**

Condition

Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type

Capacity

Permeability (Wall)

Permeability (Base)

Maintenance

Comment:

Corrective Action:

Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		39.478040,-107.643300	
Comment:						
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	YES					
Comment:	Bradenhead valve open					
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

<b>Inspected Facilities</b>				
Facility ID: 269870	Type: WELL	API Number: 045-09418	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Plunger lift			
Corrective Action:				Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Ditches	Pass					
		Gravel	Pass			
		Ditches	Pass			
Seeding	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT