

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2016

Submitted Date:

09/23/2016

Document Number:

674004436

FIELD INSPECTION FORM

Loc ID 305079 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273933	WELL	PR	07/12/2007	OW	123-22418	MOSER H 26-13	PR

General Comment:

Inspected Facilities

Facility ID: 273933 Type: WELL API Number: 123-22418 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Follow up inspection. Weeds at wellhead have been addressed.	carlilec	09/23/2016