

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2016

Submitted Date:

09/23/2016

Document Number:

673403666**FIELD INSPECTION FORM**

Loc ID 312803 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 95960Name of Operator: WEXPRO COMPANYAddress: P O BOX 45003City: SALT LAKE CITY State: UT Zip: 84145-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fredrickson, Tammy	307-352-7566	Tammy.Fredrickson@questar.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222467	WELL	PR	11/10/1994	GW	081-05474	CARL ALLEN "A" 8	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-341-3129

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
----------	---	----------	------	----------	--------	--

CONDENSATE	1	400 BBLs	STEEL AST				
Comment:							
Corrective Action:					Date:		
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate			Adequate			
Comment:							
Corrective Action:					Date:		
Contents	#	Capacity	Type	Tanak ID	SE GPS		
CONDENSATE	1	200 BBLs	HEATED STEEL AST		40.955900,-108.316830		
Comment:							
Corrective Action:					Date:		
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate			Adequate			
Comment:							
Corrective Action:					Date:		
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:					Date:		
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:					Date:		

Inspected Facilities				
Facility ID: 222467	Type: WELL	API Number: 081-05474	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: 100665 Lat: 40.955840 Long: -108.316560

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date:

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: