

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2016

Submitted Date:

09/23/2016

Document Number:

674703185

**FIELD INSPECTION FORM**

Loc ID 335823 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100185  
Name of Operator: ENCANA OIL & GAS (USA) INC  
Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	<a href="#">EnCana Inspection email</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272407	WELL	PR	07/14/2005	GW	045-10082	UNOCAL 22-4	PR
272412	WELL	PR	07/24/2005	GW	045-10077	UNOCAL 4-13DX	PR
272416	WELL	PR	10/14/2005	GW	045-10084	UNOCAL 33-4D	PR
272417	WELL	PR	09/07/2005	GW	045-10083	UNOCAL 23-4D	PR

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	800-791-7691		
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Chemical containers		
Corrective Action:			Date:
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>272407</u>	Type:	<u>WELL</u>	API Number:	<u>045-10082</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:					Date:				
Facility ID:	<u>272412</u>	Type:	<u>WELL</u>	API Number:	<u>045-10077</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:					Date:				
Facility ID:	<u>272416</u>	Type:	<u>WELL</u>	API Number:	<u>045-10084</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:					Date:				
Facility ID:	<u>272417</u>	Type:	<u>WELL</u>	API Number:	<u>045-10083</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing well</u>								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed?  P

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite?  Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed?  Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Culverts	Pass			
		Ditches	Pass			
		Gravel	Pass			
Ditches	Pass					
Seeding	Pass					
Compaction	Pass					
		Compaction	Pass			
Check Dams	Pass					
Berms	Pass					
				Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT