

FORM INSP Rev X/15	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		Inspection Date: <u>09/23/2016</u> Submitted Date: <u>09/23/2016</u> Document Number: <u>674703178</u>
FIELD INSPECTION FORM			

Loc ID 335825	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
------------------	------------------------------------	---	-------------------	--

Operator Information:

OGCC Operator Number: 100185

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

Findings:

24 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272989	WELL	PR	01/24/2014	GW	045-10202	UNOCAL 16-12D	PR
272990	WELL	PR	02/01/2014	GW	045-10203	UNOCAL 16-11D	PR
272991	WELL	PR	11/01/2005	GW	045-10204	UNOCAL 16-21D	PR
272993	WELL	PR	01/19/2005	GW	045-10205	UNOCAL 16-22D	PR
412943	WELL	PR	11/11/2011	GW	045-18691	N. Parachute MF02B-16 H17 69	PR
412946	WELL	PR	10/10/2011	GW	045-18692	N. Parachute MF03C-16 H17 69	PR
412947	WELL	PR	11/11/2011	GW	045-18693	N. Parachute MF03B-16 H17 69	PR
412948	WELL	PR	02/27/2012	GW	045-18694	N. Parachute MF02C-16 H17 69	PR
412949	WELL	PR	10/06/2011	GW	045-18695	N. Parachute MF03D-16 H17 69	PR
412950	WELL	PR	10/10/2011	GW	045-18696	N. Parachute MF04A-16 H17 69	PR
412951	WELL	PR	09/14/2011	GW	045-18697	N. Parachute MF05D-16 H17 69	PR
412952	WELL	PR	10/06/2011	GW	045-18698	N. Parachute MF05A-16 H17 69	PR
412953	WELL	PR	04/11/2012	GW	045-18699	N. Parachute MF07B-16 H17 69	PR
412962	WELL	PR	04/11/2012	GW	045-18701	N. Parachute MF12B-16 H17 69	PR
412963	WELL	PR	12/06/2012	GW	045-18702	N. Parachute MF11A-16 H17 69	PR
412966	WELL	PR	04/11/2012	GW	045-18703	N. PARACHUTE MF07C-16 H17 69	PR
412967	WELL	PR	04/11/2012	GW	045-18704	N. Parachute MF06C-16 H17 69	PR

412968	WELL	PR	02/27/2012	GW	045-18705	N. Parachute MF06B-16 H17 69	PR
412969	WELL	PR	10/06/2011	GW	045-18706	N. PARACHUTE MF02D-16 H17 69	PR
412970	WELL	PR	09/14/2011	GW	045-18700	N. Parachute MF06D-16 H17 69	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	800-791-7691		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 5		
Comment:	Chemical containers		
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS

PRODUCED WATER	1	<100 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)	80 bbls				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	272989	Type:	WELL	API Number:	045-10202	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	272990	Type:	WELL	API Number:	045-10203	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	272991	Type:	WELL	API Number:	045-10204	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	272993	Type:	WELL	API Number:	045-10205	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	412943	Type:	WELL	API Number:	045-18691	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	412946	Type:	WELL	API Number:	045-18692	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	412947	Type:	WELL	API Number:	045-18693	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	412948	Type:	WELL	API Number:	045-18694	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 412949	Type: WELL	API Number: 045-18695	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 412950	Type: WELL	API Number: 045-18696	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 412951	Type: WELL	API Number: 045-18697	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 412952	Type: WELL	API Number: 045-18698	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 412953	Type: WELL	API Number: 045-18699	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 412962	Type: WELL	API Number: 045-18701	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 412963	Type: WELL	API Number: 045-18702	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 412966	Type: WELL	API Number: 045-18703	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:

Facility ID: <u>412967</u>	Type: <u>WELL</u>	API Number: <u>045-18704</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>Producing well</u>			
Corrective Action:		Date:		
Facility ID: <u>412968</u>	Type: <u>WELL</u>	API Number: <u>045-18705</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>Producing well</u>			
Corrective Action:		Date:		
Facility ID: <u>412969</u>	Type: <u>WELL</u>	API Number: <u>045-18706</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>Producing well</u>			
Corrective Action:		Date:		
Facility ID: <u>412970</u>	Type: <u>WELL</u>	API Number: <u>045-18700</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:	<u>Producing well</u>			
Corrective Action:		Date:		

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? P

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
Berms	Pass					
Seeding	Pass					
Compaction	Pass					
Ditches	Pass					
Check Dams	Pass					
Slope Roughening	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703178	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3961036