

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2016

Submitted Date:

09/23/2016

Document Number:

674703184**FIELD INSPECTION FORM**

Loc ID 335598	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 23 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																																																							
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>																																																																																																																																											
Contact Information: <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Inspections, General</td> <td>970-285-2665</td> <td>cogcc.inspections@encana.com</td> <td>EnCana Inspection email</td> </tr> </table>					Contact Name	Phone	Email	Comment	Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email																																																																																																																															
Contact Name	Phone	Email	Comment																																																																																																																																								
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email																																																																																																																																								
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>284957</td><td>WELL</td><td>PR</td><td>06/05/2006</td><td>GW</td><td>045-12325</td><td>N PARACHUTE MF10C N04 696</td><td>PR</td></tr> <tr><td>284958</td><td>WELL</td><td>PR</td><td>02/01/2014</td><td>GW</td><td>045-12324</td><td>N PARACHUTE MF11D N04 696</td><td>PR</td></tr> <tr><td>284959</td><td>WELL</td><td>PR</td><td>06/05/2006</td><td>GW</td><td>045-12323</td><td>N PARACHUTE WF17A N04 696</td><td>PR</td></tr> <tr><td>284960</td><td>WELL</td><td>PR</td><td>06/05/2006</td><td>GW</td><td>045-12322</td><td>N PARACHUTE MF16C N04 696</td><td>PR</td></tr> <tr><td>284961</td><td>WELL</td><td>PR</td><td>01/08/2007</td><td>GW</td><td>045-12321</td><td>N PARACHUTE MF09C N04 696</td><td>PR</td></tr> <tr><td>284962</td><td>WELL</td><td>PR</td><td>06/05/2006</td><td>GW</td><td>045-12320</td><td>N PARACHUTE MF16A N04 696</td><td>PR</td></tr> <tr><td>284963</td><td>WELL</td><td>PR</td><td>01/01/2010</td><td>GW</td><td>045-12319</td><td>N. PARACHUTE MF12D N04 696</td><td>PR</td></tr> <tr><td>284964</td><td>WELL</td><td>PR</td><td>06/05/2006</td><td>GW</td><td>045-12318</td><td>N PARACHUTE MF09A N04 696</td><td>PR</td></tr> <tr><td>284965</td><td>WELL</td><td>PR</td><td>01/01/2010</td><td>GW</td><td>045-12317</td><td>N.PARACHUTE MF 18C N04 696</td><td>PR</td></tr> <tr><td>284966</td><td>WELL</td><td>PR</td><td>06/05/2006</td><td>GW</td><td>045-12316</td><td>N PARACHUTE MF15C N04 696</td><td>PR</td></tr> <tr><td>284967</td><td>WELL</td><td>PR</td><td>06/05/2006</td><td>GW</td><td>045-12315</td><td>N PARACHUTE MF17C N04 696</td><td>PR</td></tr> <tr><td>284968</td><td>WELL</td><td>PR</td><td>06/05/2006</td><td>GW</td><td>045-12314</td><td>N PARACHUTE MF18A N04 696</td><td>PR</td></tr> <tr><td>300233</td><td>WELL</td><td>PR</td><td>12/05/2009</td><td>GW</td><td>045-17863</td><td>N. PARACHUTE MF10A-4 N04 696</td><td>PR</td></tr> <tr><td>300234</td><td>WELL</td><td>PR</td><td>01/14/2010</td><td>GW</td><td>045-17862</td><td>N.PARACHUTE MF 18A-4 N04 69</td><td>PR</td></tr> <tr><td>300235</td><td>WELL</td><td>PR</td><td>12/30/2009</td><td>GW</td><td>045-17861</td><td>N.PARACHUTE MF10C-4 M04 696</td><td>PR</td></tr> <tr><td>300236</td><td>WELL</td><td>PR</td><td>12/30/2009</td><td>GW</td><td>045-17860</td><td>N. PARACHUTE MF11A-4 N04 696</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	284957	WELL	PR	06/05/2006	GW	045-12325	N PARACHUTE MF10C N04 696	PR	284958	WELL	PR	02/01/2014	GW	045-12324	N PARACHUTE MF11D N04 696	PR	284959	WELL	PR	06/05/2006	GW	045-12323	N PARACHUTE WF17A N04 696	PR	284960	WELL	PR	06/05/2006	GW	045-12322	N PARACHUTE MF16C N04 696	PR	284961	WELL	PR	01/08/2007	GW	045-12321	N PARACHUTE MF09C N04 696	PR	284962	WELL	PR	06/05/2006	GW	045-12320	N PARACHUTE MF16A N04 696	PR	284963	WELL	PR	01/01/2010	GW	045-12319	N. PARACHUTE MF12D N04 696	PR	284964	WELL	PR	06/05/2006	GW	045-12318	N PARACHUTE MF09A N04 696	PR	284965	WELL	PR	01/01/2010	GW	045-12317	N.PARACHUTE MF 18C N04 696	PR	284966	WELL	PR	06/05/2006	GW	045-12316	N PARACHUTE MF15C N04 696	PR	284967	WELL	PR	06/05/2006	GW	045-12315	N PARACHUTE MF17C N04 696	PR	284968	WELL	PR	06/05/2006	GW	045-12314	N PARACHUTE MF18A N04 696	PR	300233	WELL	PR	12/05/2009	GW	045-17863	N. PARACHUTE MF10A-4 N04 696	PR	300234	WELL	PR	01/14/2010	GW	045-17862	N.PARACHUTE MF 18A-4 N04 69	PR	300235	WELL	PR	12/30/2009	GW	045-17861	N.PARACHUTE MF10C-4 M04 696	PR	300236	WELL	PR	12/30/2009	GW	045-17860	N. PARACHUTE MF11A-4 N04 696	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																																				
284957	WELL	PR	06/05/2006	GW	045-12325	N PARACHUTE MF10C N04 696	PR																																																																																																																																				
284958	WELL	PR	02/01/2014	GW	045-12324	N PARACHUTE MF11D N04 696	PR																																																																																																																																				
284959	WELL	PR	06/05/2006	GW	045-12323	N PARACHUTE WF17A N04 696	PR																																																																																																																																				
284960	WELL	PR	06/05/2006	GW	045-12322	N PARACHUTE MF16C N04 696	PR																																																																																																																																				
284961	WELL	PR	01/08/2007	GW	045-12321	N PARACHUTE MF09C N04 696	PR																																																																																																																																				
284962	WELL	PR	06/05/2006	GW	045-12320	N PARACHUTE MF16A N04 696	PR																																																																																																																																				
284963	WELL	PR	01/01/2010	GW	045-12319	N. PARACHUTE MF12D N04 696	PR																																																																																																																																				
284964	WELL	PR	06/05/2006	GW	045-12318	N PARACHUTE MF09A N04 696	PR																																																																																																																																				
284965	WELL	PR	01/01/2010	GW	045-12317	N.PARACHUTE MF 18C N04 696	PR																																																																																																																																				
284966	WELL	PR	06/05/2006	GW	045-12316	N PARACHUTE MF15C N04 696	PR																																																																																																																																				
284967	WELL	PR	06/05/2006	GW	045-12315	N PARACHUTE MF17C N04 696	PR																																																																																																																																				
284968	WELL	PR	06/05/2006	GW	045-12314	N PARACHUTE MF18A N04 696	PR																																																																																																																																				
300233	WELL	PR	12/05/2009	GW	045-17863	N. PARACHUTE MF10A-4 N04 696	PR																																																																																																																																				
300234	WELL	PR	01/14/2010	GW	045-17862	N.PARACHUTE MF 18A-4 N04 69	PR																																																																																																																																				
300235	WELL	PR	12/30/2009	GW	045-17861	N.PARACHUTE MF10C-4 M04 696	PR																																																																																																																																				
300236	WELL	PR	12/30/2009	GW	045-17860	N. PARACHUTE MF11A-4 N04 696	PR																																																																																																																																				

300237	WELL	PR	02/10/2011	GW	045-17859	N.PARACHUTE MF06D-4 N04 696	PR
301809	WELL	PR	12/30/2009	GW	045-18279	N. PARACHUTE MF15B-4 N04 696	PR
301810	WELL	PR	12/30/2009	GW	045-18280	N. PARACHUTE MF07B-4 N04 696	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Plunger Lift	# 19		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical containers		
Corrective Action:		Date:	
Type: Gas Meter Run	# 19		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 19		
Comment:	Gas lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS	
----------	---	----------	------	----------	--------	--

PRODUCED WATER	1	<100 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)	80 bbls					
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	284957	Type:	WELL	API Number:	045-12325	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284958	Type:	WELL	API Number:	045-12324	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284959	Type:	WELL	API Number:	045-12323	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284960	Type:	WELL	API Number:	045-12322	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284961	Type:	WELL	API Number:	045-12321	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284962	Type:	WELL	API Number:	045-12320	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284963	Type:	WELL	API Number:	045-12319	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284964	Type:	WELL	API Number:	045-12318	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	284965	Type:	WELL	API Number:	045-12317	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284966	Type:	WELL	API Number:	045-12316	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284967	Type:	WELL	API Number:	045-12315	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284968	Type:	WELL	API Number:	045-12314	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	300233	Type:	WELL	API Number:	045-17863	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	300234	Type:	WELL	API Number:	045-17862	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	300235	Type:	WELL	API Number:	045-17861	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	300236	Type:	WELL	API Number:	045-17860	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	300237	Type:	WELL	API Number:	045-17859	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	301809	Type:	WELL	API Number:	045-18279	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	301810	Type:	WELL	API Number:	045-18280	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? P

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Check Dams	Pass					
Berms	Pass					
		Ditches	Pass			
		Gravel	Pass			
				Material Handling And Spill Prevention	Pass	
Seeding	Pass					
Gravel	Pass					
Compaction	Pass					
Ditches	Pass					
		Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703184	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3961030