



Photo 1. View from the western corner of the project area facing center. The majority of the well pad is revegetated with desirable vegetation such as needle and thread grass (*Hesperostipa neomexicana*), smooth brom (*Bromus inermis*), and western wheatgrass (*Pascopyrum smithii*).



Photo 2. View of the northwestern portion of the project area (on right of fence). Well pad is revegetated and fence needs to be removed.



Photo 3. View of the southwestern portion of the project area (left of the fence).



Photo 4. View of musk thistles (*Carduus nutans*) within the project area.



Photo 5. View of Canada thistles (*Cirsium arvense*) within the project area.



Photo 6. View of the access road that needs to be reclaimed.



Photo 7. View of the beginning of Transect 1, within the project disturbance facing southwestward.



Photo 8. View of the beginning of Transect 2, within the reference area facing southwestward.