

Petrohunter – 10200  
Buckskin mesa unit #2574  
Api 05-103-10062  
Location id # 316228

By Kyle Granahan

9/22/2016



Sign at entrance of location – wrong operator, no access road, no emergency #  
10/22/2015 9/22/2016



Debris & trailers on location – top pictures 10/22/2015 bottom 9/22/2016



September 22, 2016



Inspection photos location id 316228



Ag equipment and stored materials – top pictures 10/22/2015, bottom 9/22/2016



September 22, 2016



Inspection photos location id 316228



Wellhead

10/22/2015

9/22/2016