

Petrohunter – 10200
BMU #2520
Api 05-103-10230
Location id # 316316

by Kyle Granahan

9/22/2016



Sign at entrance of location – wrong operator, invalid emergency #, no access road
10/22/2015 9/22/2016



Irrigation pipe on location – top 10/22/2015, bottom 9/22/2016



September 22, 2016

Inspection photos location id 316316



Ag equipment on location – top 10/22/2015, bottom 9/22/2016



September 22, 2016



Inspection photos location id 316316



Wellhead – no sign, vegetation

10/22/2015

9/22/2016