

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2016

Submitted Date:

09/26/2016

Document Number:

685500959**FIELD INSPECTION FORM**Loc ID 319943 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 70385Name of Operator: SMITH ENERGY CORPAddress: 12706 SHILOH RDCity: GREELEY State: CO Zip: 80631**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Glen	970-330-7034	smithenergycorp@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201961	WELL	PR	05/22/1989	GW	001-07365	ROBIN LYNN 1	PR

General Comment:

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: EMERGENCY CONTACT NUMBER OK

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:	SE CORNER N39.79801 W-104.26181		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	SE CORNER N39.79801 W-104.26181		
Corrective Action:		Date:	
Type: Plunger Lift	#		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	SE CORNER N39.79801 -104.26181		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:	NETTING OVER WATER TANK				
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	2	200 BBLS	STEEL AST		39.798010,-104.261810
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	201961	Type:	WELL	API Number:	001-07365	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION

Pass

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Pass

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____ P

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____ Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
INTERMITTER CONTROLLER ON WELLHEAD	montoyaj	09/26/2016