

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2016

Submitted Date:

09/26/2016

Document Number:

680401051

**FIELD INSPECTION FORM**

Loc ID 312363 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 601 28 1/4 ROAD #D  
City: GRAND JUNCTION State: CO Zip: 81506

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Bankert, Wayne	970-683-5419	wbankert@laramie-energy.com	<a href="#">Sr. Regulatory &amp; Environmental Coordinator</a>
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	<a href="#">Field Inspector</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221319	WELL	IJ	09/13/2012	DSPW	077-05106	BUZZARD CREEK 12-4	AC

**General Comment:**

[UIC-MIT.](#)

**Location**

**Lease Road:**

	Type Access		
comment:			
Corrective Action:			Date:
	Type Main		
comment:			
Corrective Action:			Date:

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type LOCATION		
Comment:			
Corrective Action:			Date:

**Equipment:**

			corrective date
Type: Prime Mover	# 1		
Comment:	Pump and filters in housing.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	2	400 BBLs	HEATED STEEL AST		39.296405,-107.727211
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	6	300 BBLs	STEEL AST		39.296405,-107.727211
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 221319 Type: WELL API Number: 077-05106 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>COZZ</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>10/21/2015</u>
			AnnMTReq: _____

Comment:

Corrective Action:  Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: 5 Year Tbg psi: 1650 Csg psi: 1402 BH psi: 0

Insp. Status: Pass

Comment:

Corrective Action:  Date: \_\_\_\_\_