



Photo#1: Site Meeting; Location Final Land use will be Crop Ground.

September 9, 2016

Inspection Photos: Silver Loc#081-06682



Photo#2: Some Debris still on Location, Contractor will remove

September 9, 2016

Inspection Photos: Silver Loc#081-06682